CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20220348Address:2621 SW HOOK FARM LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Thursday, September 01, 2022
Corrective Action Required:			
1 Misc	-Address rafters landin -address rafters to ceili -address top plate pene -nail top plate to heade -protect NM Within 6' of -address over bored stu -seal gaps and penetration wall) -address top plates lap -nail cspf at rear living -address 2x4 payed flat -all anchor bolts in base -seal gap in fire block in -mid way strap 2" dwv -seal penetrations in R -seal penetrations in R -seal penetrations in R -seal penetrations in R	ng joist connections the etration NE er at garage portal fram of attic access uds for service entry in tions into furr down in ped less than 24" dinir room windows to design for furr downs ement to be tight n bed 4 S wall n bed 4 S wall n bed 4 closet A joist space above base ed 3 closet to ceiling sp A joist space above be	nroughout nes per design n garage pantry (see beam and entry ng room gn sement linen closet pace d 3

Comments: