## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20215945

Misc

Address: 2101 SE HAMBLEN RD, LEES SUMMIT, MO 640822620 SE RANSON RD, LEES SUMMIT, MO

640821971 SE HAMBLEN RD, LEES SUMMIT, MO 640821240 SE HOOK LN, LEES SUMMIT,

On Monday 8-29-2022. Redford resumed Sanitary Install. and place MH 54-21

MO 640821745 SE HAMBLEN RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                               |        | Inspector:  | Outcome:   | Date:                        |
|---|--------|---|--|------------------------------|
| Sanitary Sewer Construction<br>Inspection |        | Tom Taylor  | Partial  | Thursday, September 01, 2022 |
| Informational:                            |        |   |  |                              |
| 1   | Misc   | 7-13-22 RH. Interceptor portion of project is down due to pipe mender missing a part. MH-14 was damaged while test pit was being dug. Contractor knew and was going to replace. |  |                              |
| Informational:                            |        |   |  |                              |
| 2   | Misc   | On Thursday day the contractor resumed Sanitary Sewer installation. Contractor installed approx. 120 LF of 30" plastic pipe and back filled pipe.                               |  |                              |
| Informational:                            |        |   |  |                              |
| 3   | Misc   | On Friday, 8-13-2022 Redford Excavating placed approx 100LF of 30" Pipe and backfilled pipe.  |  |                              |
| Informational:                            |        |   |  |                              |
| 4   | Misc   | sewer interceptor movem   | eek. On Thursday, 8-18-202<br>nent to next man hole. Supp<br>oe her Tuesday or Wednesd | olied wrong Man Hole         |
| Informati                                 | onal:  | due to a wrong made stru  | ord could not move forward cture. Contractor moved bage graded throughout project      | ck to water crossings        |
| miomiati                                  | Oliul. |   |  |                              |

and installed 8" drop for existing sewer connection. Contractor placed approx 100 LF of 24" plastic sewer pipe and compacted.

On Tuesday 8-30-2022. Redford resumed sewer installation. Between Man Hole 54-21 to 54-20. Contractor installed approx 140 LF of 24" plastic pipe. Contractor also poured concrete for the 8" drop installed day before. And back filled trench.

On Wednesday, 8-31-2022 Redford resumed sewer installation placing 24" plastic pipe towards man hole 54-20. Contractor installed approx 160LF of pipe and set man hole 54-20 and back filled trench.

On Thursday, 9-01-2022, Redford Excavating found that Man Hole #20 had the seals reversed for pipe entrances and another Man Hole bottom section had to be made. The section won't be available until Wednesday of next week. This is the Labor Day weekend. Contractor completed some clean up and also placed some rip-rap at various locations.

## **Comments:**