

August 31, 2022


Trumark Homes 1108 NW Woodbury Dr. Grain Valley, Mo 64029

RE: Field Issue of non-continuous deck posts for Lot # 134 4804 NE Freehold Ct. Lee's Summit, MO 64064

• One covered deck post is noncontinuous.

Recommended modifications:

- Install (2) 24" length CS-16 straps on sides of non-continuous post per manufacturer's spec's.
- Shim gaps between posts with like material.



Sincerely,

14

Bradley Huxol, PE

