CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20215945 Address: 2101 SE HAMBLEN RD, LEES SUMMIT, MO 640822620 SE RANSON RD, LEES SUMMIT, MO 640821971 SE HAMBLEN RD, LEES SUMMIT, MO 640821240 SE HOOK LN, LEES SUMMIT, MO 640821745 SE HAMBLEN RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Sanitary Sewer Construction Inspection		Tom Taylor	Partial	Thursday, September 08, 2022	
Informati	onal:				
1	Misc		ortion of project is down du s damaged while test pit wa place.	• •	
Informational:					
2	Misc	On Thursday day the contractor resumed Sanitary Sewer installation. Contractor installed approx. 120 LF of 30" plastic pipe and back filled pipe.			
Informational:					
3	Misc	On Friday, 8-13-2022 Redf backfilled pipe.	ord Excavating placed appro	ox 100LF of 30" Pipe and	
Informational:					
4	Misc	sewer interceptor movem	reek. On Thursday, 8-18-202 nent to next man hole. Supp pe her Tuesday or Wednesc	olied wrong Man Hole	
1		due to a wrong made stru	ord could not move forward cture. Contractor moved ba graded throughout projec	ck to water crossings	
Informational: 5 Misc		On Monday 8-29-2022 Ro	dford resumed Sanitary Ins	tall and place MH 5/1-21	
J	IVIISC	011 WOTUAY 0-23-2022. RE	arora resumed Samualy IIIS	tan. and place with 34-21	

		and installed 8" drop for existing sewer connection. Contractor placed approx 100 LF of 24" plastic sewer pipe and compacted.
		On Tuesday 8-30-2022. Redford resumed sewer installation. Between Man Hole 54-21 to 54-20. Contractor installed approx 140 LF of 24" plastic pipe. Contractor also poured concrete for the 8" drop installed day before. And back filled trench.
		On Wednesday, 8-31-2022 Redford resumed sewer installation placing 24" plastic pipe towards man hole 54-20. Contractor installed approx 160LF of pipe and set man hole 54-20 and back filled trench.
		On Thursday, 9-01-2022, Redford Excavating found that Man Hole #20 had the seals reversed for pipe entrances and another Man Hole bottom section had to be made. The section won't be available until Wednesday of next week. This is the Labor Day weekend. Contractor completed some clean up and also placed some rip-rap at various locations.
Informati	onal:	
6	Misc	On Thursday, 9-08-2022. Redford Excavating placed man hole 54-20 and 4 sections of 24" ductile pipe. Contractor are at the last encasement to install an they will pour on tomorrow.

Comments: