

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20210263

Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	Michael Harkins	Failed	Friday, September 09, 2022

Corrective Action Required:

1 Misc

BUILDING A HARD LIDS:

5001-PROVIDE ACCESS PANEL FOR J BOXES

5007-SECURE MC, COMPLETE ELECTRICAL

4001-OK

4007-COMPLETE MECHANICAL, PROVIDE ACCESS PANELS FOR J BOXES AND DAMPERS, COMPLETE SPRINKLER DROPS, SECURE MC

3001-OK

3007- PROVIDE ACCESS PANELS FOR J BOXES AND DAMPERS, COMPLETE SPRINKLER DROPS, SECURE MC

2001-PROVIDE ACCESS PANELS FOR J BOXES AND DAMPERS, SECURE MC

2007-PROVIDE ACCESS PANELS FOR J BOXES AND DAMPERS

Corrective Action Required:

2 SECOND FLOOR

AREA "A"

Room 2004 pass

Corridor 2007 soffits penetrations missing fire box missing above fire door

Room 2006 pass

Room 2008 complete ducts & fire caulk

Room 2010 fire caulk seal penetrations

Room 2005 fire caulk upward penetrations, complete condensation line

Corrective Action Required:

3

THIRD FLOOR

AREA "A"

3004 pass

3005 pass

3006 pass

3008 complete duct work

3010 fire tape ceiling line

Corridor 3007 soffits penetrations missing fire box above fire door

Corrective Action Required:

4

FOURTH FLOOR

AREA "A"

4004 pass

4005 seal upward penetration line set behind door

4008 complete duct work, fire tape sprinkler line patch

4010 seal penetrations above drop ceiling

4006 complete duct work

Corrective Action Required:

5

FIFTH FLOOR

AREA "A"

5004 seal upward penetrations, provide cover open box

5006 complete duct work

5008 ok

5010 seal upward penetrations

Corridor 5007 soffit at fire door ok to cover

5013 ok

**Comments:**