## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Above Ceiling Inspection		Inspector:	Outcome:	Date:
		Robb Popp	Partial	Tuesday, September 13, 2022
Correctiv	e Action Required:			
1 Correctiv	Misc e Action Required:	HARD LIDS		
2	SECOND FLOOR	AREA "A"		
		Room 2004 pass		
		Corridor 2007 soffit	ts penetrations missing fi	re box missing above fire door
		Room 2006 pass		
		Room 2008 ok		
		Room 2010 ok		
		Room 2005 access p		
		2002-access panels	for dampers, seal penetr	ations
Correctiv	e Action Required:			
3	THIRD FLOOR	AREA "A"		
		3004 pass		
		3005 pass		
		3006 pass		
		3008 ok		
		3010 ok		
Correctiv	e Action Required:			
4	FOURTH FLOOR	AREA "A"		

		4004-ok 4005-access panels 4008-ok 4010-ok 4006-seal penetrations
Corrective	e Action Required:	
5	FIFTH FLOOR	AREA "A"
		5004 seal upward penetrations, provide cover open box
		5006-ok
		5008 ok
		5010-ok
		Corridor 5007 soffit at fire door ok to cover
		5013 ok
		5007-ok
		5001-ok
		5005-access panels
		5004-dampers
		5006-seal gaps at dampers

## Comments: