CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Above Ceiling Inspection		Robb Popp	Partial	Wednesday, September 21, 2022
Corrective	Action Required:			
1	Misc	HARD LIDS		
	Action Required:			
2	SECOND FLOOR	AREA "A"		
		Room 2004 pass		
		•	trations missing fire box mi	issing above fire door
		Room 2006 pass	U U	C
		Room 2008 ok		
		Room 2010 ok		
		Room 2005 access panels		
		2002-access panels for dar	npers, seal penetrations	
Corrective Action Required:				
3	THIRD FLOOR	AREA "A"		
		3004 pass		
		3005 pass		
		3006 pass		
		3008 ok		
		3010 ok		
Corrective Action Required:				
4	FOURTH FLOOR	AREA "A"		

	4004-ok 4005-access panels 4008-ok 4010-ok 4006-OK Corridor 417 soffits ok
Corrective Action Required:	
5 FIFTH FLOOR	AREA "A" 5004 seal upward penetrations, provide cover open box 5006-ok 5008 ok 5010-ok Corridor 5007 soffit at fire door ok to cover 5013 ok 5007-ok 5007-ok 5001-ok 5005-access panels 5004-dampers 5006-OK ALL SOFFIT FRAMING IN CORRIDORS BUILDING B OK

Comments: