CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210263Address:1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: Above Ceiling Inspection | | Inspector: | Outcome: | Date: | |
|---|--------------------|---|-------------|-------------------------------|--|
| | | Robb Popp | Partial | Friday, September 23, 2022 | |
| Corrective | Action Required: | | | | |
| 1 | Misc | HARD LIDS | | | |
| Corrective | e Action Required: | | | | |
| 2 | SECOND FLOOR | AREA "A" | | | |
| | | Room 2004 pass | | | |
| | | Corridor 2007 soffits penetrations missing fire box missing above fire door | | | |
| | | Room 2006 pass | | | |
| | | Room 2008 ok | | | |
| | | Room 2010 ok | | | |
| | | Room 2005 access p | | | |
| | | 2002-access panels | for dampers | | |
| | | 2017 soffits ok | | | |
| | e Action Required: | | | | |
| 3 | THIRD FLOOR | AREA "A" | | | |
| | | 3004 pass | | | |
| | | 3005 pass | | | |
| | | 3006 pass | | | |
| | | 3008 ok | | | |
| | | 3010 ok | | | |
| | | 3017 sofffits ok | | | |

Corrective Action Required:

| 4 | FOURTH FLOOR | AREA "A" |
|----------|---------------------|---|
| | | 4004-ok |
| | | 4005-access panels |
| | | 4008-ok |
| | | 4010-ok |
| | | 4006-OK |
| | | Corridor 417 soffits ok |
| Correcti | ve Action Required: | |
| 5 | FIFTH FLOOR | AREA "A" |
| | | 5004 seal upward penetrations, provide cover open box |
| | | 5006-ok |
| | | 5008 ok |
| | | 5010-ok |
| | | Corridor 5007 soffit at fire door ok to cover |
| | | 5013 ok |
| | | 5007-ok |
| | | 5001-ok |
| | | 5005-access panels |
| | | 5004-dampers |
| | | 5006-OK |
| | | ALL SOFFIT FRAMING IN CORRIDORS BUILDING B OK |
| | | |

Comments: