## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20210775 Address: 1201 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	n:	Inspector:	Outcome:	Date:
Erosion Sediment Control (ESC) Inspection		Ronald Paynter	Partial	Monday, October 03, 2022
Informatio	onal:			
1	Misc	No erosion issues to repor	t on the job site today. RP :	3-23-22
Informatio	onal:			
2	Misc	Another rain day, still no erosion issues to report. RP 3-24-22		
Corrective	Action Required:			
3		Curb and field inlets are fu RP 4-4-22	Ill of silt and there is excess	s silt in the roadways.
Corrective Action Required:				
4	Misc	Curb inlets are still full of s	silt. RP 4-8-22	
Informational:				
5	Misc	Curb inlets have been clea	ned out. RP 4-11-22	
Informational:				
6	Misc	Welch Erosion was on site	installing silt fencing. RP 4	-15-22
Informational:				
7		existing house at 2787 SW	illed to prevent dirt and erc 11th Terr. Also need erosio walks as mud and silt are bu ations. 5/24/22 ES	n control installed
		Erosion control measures i	nstalled and functioning. 8	/8/22 ES
		Erosion control measures i	nstalled and functioning. 8	/15/22 ES

Erosion control measures installed, intact, and functioning. 10/3/22 ES

Comments: