

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20213808  
Address: 3817 SW MARYVILLE PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Codes Residential</b>	Patrick Schonfeldt	Failed	Thursday, October 13, 2022

Corrective Action Required:

1	Misc	-cover plate should be flush with surface at kitchen wall switch -provide security screws basement walkout, (2) 3" screws at each hinge and (2) 3" screws at strike plate -basement light fixture broke -seal penetrations in siding, seal across top of AC disconnect and meter can -sod cannot be less than 6" from siding, see rear of house -(2) 1/2" through bolts required at each post/beam connection at deck -downspout at front stairs, discharge 36" from foundation
---	------	---

Comments: