



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	GRD KIRKSVILLE, LLC - GREEN RELEAF		
ADDRESS	201 SE M 291 HWY, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	KSJ CONSTRUCTION:	TELEPHONE	(209) 585-5868
ADDRESS	6703 HWY JJ FLORENCE, MO 65329 Primary: (209) 585-5868 Cell: <NO CELL PHONE>		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	
2. _____	
3. _____	
4. _____	

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Craig Hill	Not Required	Monday, October 24, 2022
Sprinkler - Hydrostatic Test	Craig Hill	Not Required	Monday, October 24, 2022
Sprinkler - Flow Test	Craig Hill	Not Required	Monday, October 24, 2022

Occupancy Inspection - Fire Craig Hill Failed Tuesday, October 25, 2022

Corrective Action Required:

- 1 Label exterior door with sprinkler room.
Move Knox box to the rear door.
Interior exit door must drop when alarm sounds for water flow in building.

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
October 25, 2022	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	