CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20222754 Address: 2217 NW KILLARNEY LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Residential		Michael Harkins	Failed	Tuesday, November 01, 2022
Corrective	Action Required:			
1	Miscellaneous Correction	No deck pier inspection on Covered deck shall have 1 Secure deck fire place Secure gas line deck firepla Seal fire blocking deck firep Missing hanger master bed Missing truss screw / H2.5 Missing truss screws / H2.5 Missing truss screws / H2.5 Solid block sheathing break Seal upward penetration a Seal upward penetration a Seal upward penetration a Seal b vent chase garage / Fire blocking above refrige Seal fire blocking dead spa Solid block sheathing break Solid block sheathing break Solid block nail sheathing of Provide CS-PF exterior brace Seal upward penetration ri Provide CS-PF window left	roof vent & 4 soffit vents pe ace blace d each side fire place 5s foyer rews / H2.5s front porch front door < garage at GFCI bove GFCI master closet rator ce at oven < under window office corner ft porch / office cing at foyer per plan ght of fireplace	r plan
		Snow blocking above deck	•	

Complete CS-PF nailing deck door Fire stop tub trap Provide anchor bolts SCH 40 columns Tighten anchor bolt bed 4 closet Provide electrical nail guard at bed 3 vanity Provide joist hangers unfinished area near gas line entry point Provide flashing above horizontal window trim

Comments: