

FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1								
☐ CHANGES								
BUSINESS NAME	GRD KIRKSVILLE, LLC - GREEN RELEAF							
ADDRESS	201 SE M 291 HWY, LEES SUMMIT, MO 64063							
OWNER/OPERATOR NAME	KSJ CONS	STRUCTION	:			TELEPHON	E ((209) 585-5868
ADDRESS	6703 HWY FLORENC Primary: (2 Cell: <no< td=""><td></td><td></td><td></td><td></td><td></td></no<>							
		EMERGE	NCY CONTA	CT INFOR	MATION			
NAME	TELEPHONE							
1								
2.								
3.								
4.								
		L	OSS REDUCT	TION TYPE	.			
☐ Occupancy ☐ Se	mi-Annual	☐ Ann	ual 🔲 Life S	afety	☐ Sp	rinkler		Hazardous Material Permit
☐ Complaint ☐ Ex	plosive Storaç	ge 🔲 UST	☐ Post-	ncident		en Burning		Other
CLASS:	Мар#:	PFA#:	KNOX BO	X:	KNOX	LOCATION:		PERMIT#
		LOS	S REDUCTIO	N NARRA	ΓIVE			
☐ NO VIOLATIONS	☐ NO VIOLATIONS NOTED ☐ ALL VIOLATIONS RESOLVED							
Last Inspection	1st Inspection		2nd Inspection		3rd Inspec	tion	4	4th Inspection
INSPECTION	IN	SPECTOR		OUTCOME	<u> </u>	DATE		
Alarm Test	Craig Hill			Not Required		Monday,	Octo	ober 24, 2022
Sprinkler - Hydrostati	c Test C	raig Hill		Not Requ	uired	Monday,	Octo	ober 24, 2022
Sprinkler - Flow Test		Craig Hill		Not Required		Monday.	Octo	ober 24. 2022

Occupancy Inspection - Fire	e Craig Hill	Failed	Tuesday, October 25, 2022						
Corrective Action Required: 1 Label exterior door with sprinkler room. Move Knox box to the rear door. Interior exit door must drop when alarm sounds for water flow in building.									
Occupancy Inspection - Fire	Craig Hill	Passed	Wednesday, November 02, 2022						
Corrective Action Required: All life safety was appropriate. Okay to occupy with approval from codes.									
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UI REQUIRED?	RESPONSIBLE SIGNATURE						
November 02, 2022	Craig Hill	☐ Yes ☐ No							