

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20202008
Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Record Drawing Review	Eric Sharp	Partial	Wednesday, November 02, 2022

Corrective Action Required:

1 Misc

Water line is missing 1 valve riser lid at Patch and O'Brien. Extra fire hydrant on O'Brien, needs to be removed from the plans (it was never installed). Existing sanitary manhole on line 1 is buried under silt. Storm end sections 1-1, 2-1, 3-1, 4-1, 5-1 and 7-1 need excess silt removed. End sections 3-1 and 4-1 need additional rip rap. End section 4-1 has standing water and will need to be regraded. Storm manhole 3-2 is buried under silt. Field inlets 9-2 and 10-2 need trash racks installed. Field inlet 10-2 also needs boarding and debris removed. RP 4-5-22

Water line 1 is still missing valve riser lid at Patch and O'Brien. Storm end sections had been cleaned up and additional rip rap added where necessary. 9-2 and 10-2 inlets also had trash racks installed and debris removed. 11/2/22
ES

Comments: