

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20202008  
Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Punch List Inspection</b>	Eric Sharp	Partial	Wednesday, November 02, 2022

Informational:

1          Misc

Attached is the first part of the punch list from field observations. Water line is missing 1 valve riser lid at Patch and O'Brien. Extra fire hydrant on O'Brien, needs to be removed from the plans (it was never installed). Existing sanitary manhole on line 1 is buried under silt. Storm end sections 1-1, 2-1, 3-1, 4-1, 5-1 and 7-1 need excess silt removed. End sections 3-1 and 4-1 need additional rip rap. End section 4-1 has standing water and will need to be regraded. Storm manhole 3-2 is buried under silt. Field inlets 9-2 and 10-2 need trash racks installed. Field inlet 10-2 also needs boarding and debris removed. RP 4-5-22

Water line 1 is still missing valve riser lid at Patch and O'Brien. Storm end sections have been cleaned up and additional rip rap added where necessary. 9-2 and 10-2 inlets also had trash racks installed and debris removed. 11/2/22 ES

**Comments:**