

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20215636  
Address: 451 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Sediment Control (ESC) Inspection</b>	Eric Sharp	Partial	Tuesday, November 08, 2022

Informational:	
1	Misc
	Erosion control measure installed around perimeter of project site. 9/6/22 ES
	9-20-22 RH. Erosion control is in place and in working order.
	Erosion control installed, intact and functioning. 9/26/22 ES
	Erosion control measures installed, intact, and functioning. 10/3/22 ES
	Erosion control measures installed, intact, and functioning. 10/10/22 ES
	Erosion control measures installed, intact and functioning. 10/18/22 ES
	Rain event 10/24. Erosion control measures unable to contain some runoff of open storm trenches allowing some silt to make its way through to basin on SE side of Kessler drive. Most other erosion control measures intact and functioning to contain erosion on site. 10/25/22 ES
	Erosion control measures installed, intact, and functioning. 10/31/22 ES
	Erosion control measures installed, intact, and functioning. All vehicles were parked around perimeter of site and no erosion issues noted. 11/7/22 ES

**Comments:**