

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20213808  
Address: 3817 SW MARYVILLE PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Codes Residential</b>	Patrick Schonfeldt	Failed	Friday, November 11, 2022

Corrective Action Required:

1	Misc	-basement light fixture porcelain broke, exposed NM at junction -sod cannot be less than 6" from siding, see rear of house, rock, sod, landscaping all share same requirements for clearance from siding 6", correct grade for clearance and also maintain required 6" from fall within first 10' of foundation, IRC R317.1 note 5
---	------	---

**Comments:**