

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSITE20214153

Address: 2150 NW LOWENSTEIN DR, LEES SUMMIT, MO 64081
2100 NW LOWENSTEIN DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Sediment Control (ESC) Inspection	Eric Sharp	Partial	Friday, November 18, 2022

Informational:

1 Misc

No erosion issues to report on the job site today. RP 3-23-22

Informational:

2 Misc

Another rain day, still no erosion issues to report. RP 3-24-22

Informational:

3 Misc

Rainy day, some mud along roadways on the interior portion of apartments.
7/25/22 ES

Erosion control measures still installed and functioning along outer edges of project. 8/1/22 ES

Erosion control measures still installed and functioning along outer edges of project. 8/8/22 ES

Erosion controls installed and containing issues within worksite perimeter.
8/22/22 ES

Erosion controls installed and containing any issues within perimeter.
8/29/22 ES

Erosion controls installed, intact, and functioning. 9/8/22 ES

Erosion control measures installed, intact, and functioning. 9/26/22 ES

Erosion control measures installed, intact, and functioning. 10/3/22 ES

Erosion control measures installed, intact, and functioning. 10/10/22 ES

Had an issue called in about mud and tracks coming from entrances near lots 11/12 and going along north side and behind existing apartments. Appears some construction traffic used these entrances unnecessarily. Spoke with Mike with Brinkmann, he was able to mobilize a sweeper and get these areas cleaned up and under control. 10/11/22 ES

Erosion control measures installed, intact and functioning. 10/18/22 ES

Erosion control measures installed, intact, and functioning. 11/7/22 ES

Erosion control measures install, intact and functioning. 11/18/22 ES

Comments: