CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220175

Address: 2042 SW RED BARN LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Monday, November

Residential 21, 2022

Corrective Action Required:

1 Misc

- -sheathing breaks at garage portal to occur in the middle 24" of the portal leg
- -address rafters landing on blocks throughout
- -provide proper slope for dwv above master walk in closet -fire block vertically to horizontally at NW REC room beam
- -missing top plate nailing, anchor bolts and nailing at basement cspf
- -fireblock E wall in basement bath into furr down
- -fireblock E bed 4 wall into furr down
- -address holes drilled through floor joist near service panel multiple holes

drilled closer than 2"

Comments: