CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20212347Address:146 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Mitchell Schwarz	Failed	Friday, December 30, 2022
Corrective Action Required:			
1 Misc	kitchen -lable all non GFCI rece -GFCI outlet in single ca -spark rings right and le -secondary locking devi -provide fire protection section R302.13 -provide lock outs for b heater -provide missing hange -provide missing nails a	doors 2 per hinge and op outlets where requ ptacles in unfinished s r garage nearest garag ft of basement slider ce at rear sliders for engineered I-joist reakers on hardwired rs at deck joists t deck joist hangers t bolts at each deck p e 6" see S side of house to extend 36" from four 7 3/4" see bottom step papetion and design for an	uired in kitchen and prep spaces ge door will not reset t in unfinished spaces per appliances in kitchen and water ost to beam connection e undation

-bring water meter to grade (must maintain 14"-18" from meter to lid

Comments: