CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220642

Address: 2027 SW FARM FIELD LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Thursday, January 05,

Residential 2023

Corrective Action Required:

1 Misc

-anchor bolts to be within 12" of sill plate ends but not closer than 7x the

diameter of the bolt(garage W wall)

-fire block furr outs into furr downs in garage

-fire block mud room wall space to ceiling space

-fire block pantry wall to ceiling space

-cspf nailing at front dining room window and anchoring

-strap top plate break lapped less than 24" above bed 4 bath

-repair basement slab drain

-complete cspf nailing at rear of home.

Comments: