

January 12, 2023

## **Distribution:**

Craig Bruning New Mark Homes 5207 NW Crooked Road Parkville, Missouri 64152

## Project:

21-406 Lot 106 Woodside Ridge 102 N.W. Ambersham Drive Lee's Summit, Missouri 64081

## COMPLIANCE LETTER

This letter shall serve as verification that a representative(s) from Apex Engineers, Inc. ("Apex") performed a design review of the rafter bearing condition in the garage for the above referenced project.

The triple blocking in between the ceiling joists, which rest on the exterior garage wall, may be attached to
each stud below with a Simpson CS22 strap, and the blocking may be held in place with an 8" Timberlok
structural screw to the left side of each rafter. If these two items are completed, these variations from detail
7/S3.2 are approved.

To the best of our knowledge, information and belief, construction of the above phases was in general conformance with the construction documents and approved changes.

## LIMITATIONS

Apex has performed its services in a manner consistent with the standard of care and skill ordinarily exercised by members of our profession practicing under similar circumstances. The services of Apex should not be construed as Special Inspection services or full-time observation or inspection. Apex does not insure any result, nor does it warrant or guarantee that construction was properly performed. Even with constant monitoring, some construction defects may be missed. Apex is not responsible for the means, methods, sequences, and techniques of construction, since the contractor is solely responsible those and for the quality of work, adhering to plans, specifications, and appropriate codes, and repairing defects, deficiencies or omission, regardless of whether a defect is observed.

In addition, the scope our services does not include any evaluation of the building or site for job-site safety and/or hazardous conditions. The contractor is solely responsible for safety and compliance with IRC, IBC, and OSHA standards.

Finally, Apex's scope of services does not include any environmental assessment (such as, but not limited to mold, mildew, presence of hazardous or toxic materials in the soil, surface water, ground water, etc.).

To the fullest extent permitted and allowed by law, Apex's client agrees to indemnify and hold harmless Apex and its owners, partners, officers, directors, employees, agents and sub-consultants, from and against all damage, liability and costs, including reasonable attorney's fees and cost of defense, arising out of the performance of these services, excepting only those damages, liabilities or costs attributable to the negligence or willful misconduct of Apex or its consultants.

Please call if Apex Engineers, Inc. can be of further assistance.

Best Regards, Apex Engineers, Inc.

un Ann

Connor Hobart Design Engineer

..... ٥F NUMBER Bryce D. Crady, P.E. BO 2023.U .... PROX PE -2006026494 Principal

Austin, TX 512 960-3722 Denver, CO 720 588-3222 Kansas City, MO 816 421-3222 Lawrence, KS 785 337-3222

apex-engineers.com