

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216551
Address: 3225 SW MARY ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Shawn Hoffman	Failed	Thursday, January 19, 2023

Corrective Action Required:
1 DCM5 ESC INSP DENIED REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION.

- REPAIR SILT FENCE
- REMOVE DEBRIS FROM STREET

Corrective Action Required:
2 Misc Silt fence needs repaired around property, but especially in back where draining into alley way. 5/24/22 ES

Corrective Action Required:
3 DCM1 ESC REQUIRED NO FURTHER INSP EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.

REMOVE GRAVEL AND DEBRIS FROM STREET

Comments: