CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20220896

Address: 1071 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811073 NW BLACK TWIG CIR, LEES SUMMIT, MO

640811075 NW BLACK TWIG CIR, LEES SUMMIT, MO 640811069 NW BLACK TWIG CIR,

LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Failed Friday, January 20,

Commercial 2023

Corrective Action Required:

1 Misc Throughout: Protect dryer duct 2" below top plate, Provide missing H2.5s

and ladder trusses

1069-seal penetrations at ceiling line in master bed, support dwv 1071- Address broken truss at stairwell, support dwv above bath 2, 1073-Nail corner studs at garage, address broken truss near stairs, seal

penetrations at master top pl, strap top plate at master wall

1075-Missing stud pack at garage GT, support dwv at bath 2, strap top plate at

master

Comments: