

FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1									
☐ CHANGES									
BUSINESS NAME	THE LOCA	AL PIZZERIA							
ADDRESS	805 NE I	_AKEWOOE	BLVD, LEES	SUMMIT, M	O 6	4064			
OWNER/OPERATOR NAME	D.I.G. C	ONSTRUC	TION INC:	C: TELEPHON			Ξ ((913) 954-7131	
ADDRESS	KANSA: Primary	ANCHESTE S CITY, MO : (913) 954-7 O CELL PH	64134 7131						
		EMER	GENCY CON	TACT INFOR	MA	TION			
NAME					TELI	EPHONE			
1									
2.									
3.									
4.									
			LOSS REDI	JCTION TYPI	 E				
☐ Occupancy ☐ Sen	ni-Annual	A	nnual 🔲 Life	e Safety		Sprinkler		Hazardous Material Permit	
☐ Complaint ☐ Exp	losive Sto	rage 🔲 U	ST 🔲 Po	st-Incident		Open Burning		Other	
CLASS: A-2	Мар#:	PFA#:	KNOX	(BOX:		KNOX LOCATION:		PERMIT#	
		LC	OSS REDUCT	ION NARRA	TIVI	E			
☐ NO VIOLATIONS N	IOTED			☐ ALL VI	OL#	ATIONS RESOLV	ED		
Last Inspection	1st Inspecti	on	2nd Inspectio	2nd Inspection 3rd Inspe			•	4th Inspection	
INSPECTION		INSPECTOR		OUTCOME		DATE			
Alternate Protection Systems Craig Hill				Passed			Friday, January 27, 2023		
Inspection	,	3				3 , -			
Occupancy Inspection - Fire Ben Hicks				Failed			Thursday, February 02, 2023		
Corrective Action Requir 1 Emergency E		not operation	nal, front and r	ear					

Corrective	Action Required:											
2	Emergency lighting not operational front and rear. Cieling lights shown on plans not seen.											
Corrective Action Required:												
3	Breaker box front panel cover needs to be secured in place											
Corrective Action Required:												
Multiple open electrical boxes needs cover plate installed in ceiling and around ansul fire suppression system Corrective Action Required:												
												5 Filters need to in place over cooking aplliences where ansul system installed
Corrective Action Required:												
6 PLace address on back door												
DATE OF RE	EPORT	INSPECTOR	PREVENTION REQUIRED?	N FOLLOW-UP	RESPONSIBLE SIGNATURE							
February (02, 2023	Ben Hicks	☐ Yes	□ No								