### CITY OF LEE'S SUMMIT

# Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20183861

Address: 220 SE GREEN ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Footing Inspection - Residential sysadmin Failed Tuesday, February 14,

2023

Corrective Action Required:

1 R403.1.1.2 Column no clearance

Pads

FOOTINGS. ADDED 7-920. Column pads shall be a minimum of 24 inches by 24 inches and 8 inches deep ( $24" \times 24" \times 8"$ ). Reinforcement shall consist of a minimum of three No. 4 bars each way, uniformly spaced, within each column

pad.

Corrective Action Required:

R402.2 Concrete FOUNDATION. Concrete shall have a minimum specified compressive strength

of , as shown in Table R402.2. Concrete subject to moderate or

--- failed beacuse of cleant

Corrective Action Required:

3 R506.2 Site

preparation

CONCRETE FLOORS (ON GROUND). The area within the foundation walls shall have all vegetation, top soil and foreign material removed.

Corrective Action Required:

Misc fire east wall

- sdgsgsg

=

= install outlet under stia

1. fire mast

2. oult me a

\_

#### **Comments:**