CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSUBD20215636Address:451 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Sediment Control (ESC) Inspection		Ryan Heckman	Partial	Wednesday, February 22, 2023
Informational:				
1		Erosion control measure installed around perimeter of project site. 9/6/2		
	9	9-20-22 RH. Erosion control is in place and in working order.		
	I	Erosion control installed, intact and functioning. 9/26/22 ES		
	I	Erosion control measures installed, intact, and functioning. 10/3/22 ES		
	I	Erosion control measures installed, intact, and functioning. 10/10/22 ES		
	I	Erosion control measures installed, intact and functioning. 10/18/22 ES		
	(Rain event 10/24. Erosion control measures unable to contain some runoff of open storm trenches allowing some silt to make its way through to basin on SE side of Kessler drive. Most other erosion control measures intact and functioning to contain erosion on site. 10/25/22 ES		
	I	Erosion control measures i	nstalled, intact, and functio	oning. 10/31/22 ES
			nstalled, intact, and function of site and no erosion issue	-

11-14-22 RH. Erosion control is in place and working order. One corner of the silt fence was starting to fail but not yet. This was informed to the contractor.

Erosion control measures installed, intact, and functioning. The corner of concern has not failed, but also does not appear to have been addressed. 11/21/22 ES

12-12-22 RH. Erosion control is up and in working order.

12-20-22 RH. Erosion control is up and in working order.

12-27-22 RH. Erosion control is up and in working order.

1-9-22 RH. Erosion Control is up and in working order.

1-23-23 PS Erosion control within compliance

1-25-23 PS Erosion control within compliance

1-30-23 RH. Eroison contorl is up and in working order.

2-6-23 RH. Eroison control is up and in working order.

2-13-23 RH. Erosion control is up and in working order.

2-22-23 RH. Erosion Control is up and in working order.

Comments: