CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20222621Address:2071 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Control		Mitchell Schwarz	Failed	Wednesday, February 22, 2023
Corrective	e Action Required:			
3	DCM1 ESC	EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE		
	REQUIRED NO	PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.		
	FURTHER INSP			
Corrective	e Action Required:			
4	DCM2 ESC	DEFICIENT EROSION CONT	ROL INSTALLATION. NO FU	RTHER INSPECTIONS
	DEFICIENT	UNTIL ADEQUATE EROSION	N CONTROL PROVIDED.	
	INSTALLATION			
Corrective	e Action Required:			
5	DCM3 ESC	EROSION CONTROL REQUI	RED. EROSION CONTROL SH	HALL BE IN COMPLIANCE
	REQUIRED 2 DAY	WITHIN TWO BUSINESS DA	AYS.	

Comments: