## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20225569Address:2012 NE BLUESTONE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Monday, March 06, 2023
Corrective Action Required	:		
1 Misc	<ul> <li>Tighten all anchor nu</li> <li>Secure SE cable with</li> <li>Fb all wall plate and</li> <li>Triple stud support for</li> <li>Reroute refrigerator</li> <li>Protect wiring at pan</li> <li>Provide security bloct</li> <li>Support top of hip ab</li> <li>Nail together kitcher</li> <li>Protect wiring at greater in the security at the security bloct</li> <li>Support top of hip ab</li> <li>Nail together kitcher</li> <li>Protect wiring at greater is the security at the secur</li></ul>	in 12" of meter entry floor penetrations or IvI beam at laundry/g water line and protect is try bottom wall plate skings at exterior door t bove rear dining in I beam support studs at room bottom wall plate oom cle spacing per code at se from top of fireplace om roof space; Fb master becker bottom store becker code over	if required o patio ate at rear wall and wall across rear great room er bathroom triangular wall Iroom ceiling beam

\*\*OK TO INSULATE

**Comments:**