

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20226242
Address: 807 SE MILLER ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Monday, March 06, 2023

Corrective Action Required:

1	Misc	<ul style="list-style-type: none">- Dryer exhaust duct shall have a smooth interior finish and be constructed of metal not less than 0.0157 inch with a 4" diameter. M1502.4.1 ** All the way to outside- remove copper tubing and cap gas line at old laundry- cap drain at old laundry- missing outlet cover at sump pump - outlet at sump to be single and labeled non-GFCI- GFCI outlet to be within 24" of sink in bathroom- laundry outlet to be GFCI protected - All outlets in living areas must be AFCI protected- All electrical to be brought up to 2018 code GFCI's installed were required.- label electrical panel OK to insulate and rock
---	------	--

Comments: