CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20221409Address:2022 SW RED BARN LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Monday, March 20, 2023
Corrective Action Required:			

1 Misc

-all anchor bolts to be in the middle third of sill plate and tight
-fire block furr down beam ends throughout basement -seal penetrations in R/a joist space above great room/billiards area
-fire block dead space at basement bath wall to ceiling space
-fire block basement bed room bath to bed 4 ceiling space
-fire block furr down ends in bed 4
-fire block bed 4 walls to ceiling space
-address notched floor joist at anchor bolt above furnace area

Comments: