## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20215682Address:4405 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Occupancy Inspection - Codes Residential		Alex Fischer	Failed	Wednesday, March 22, 2023	
Correc	tive Action Required:				
1	Misc	-no sidewalk inspection contact field			
		Stair rise from 1st to second floor is over 3/8 difference 7 3/4 steps top step			
		7 inches			
		-master closet can lights too close to shelves, min 12 inch to edge of fixture			
		-garage stairs over 3/8 difference between top and bottom			
		-seal angled box out in garage			
		-stair rise inconsistent basement stairs			
		-Missing anti-siphor	n device at basement hos	e bib	

-provide inch and a half bearing at landing and deck

**Comments:**