CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220917

Address: 3533 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Kyle Beard Failed Tuesday, April 18, 2023

Residential

Corrective Action Required:

1 Miscellaneous Correction

- -need fire blocking in the chase ceiling in the garage
- -fire blocking in the cavity A/C wall by garage entry bathroom is broken and
- -fire block 1/2 bathroom wall off the garage in fur down
- -fire block kitchen wall/duct chase at the end of the fur down
- -master bathroom vanity by 2 inch PVC vent pipe needs to be strapped at the
- top plate
- -metal conduit for sump pump needs a plastic bushing on top at electrical

wire

Comments: