CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20215682Address:4405 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Failed	Friday, April 21, 2023

Corrective Action Required:

1 Misc

- -Stair rise from 1st to second (wood) floor is over 3/8 difference 7 3/4 steps top step 7 inches
 - -garage stairs over 3/8 difference between top and bottom
 - -basement stair to carpet platform stair riser is over 7 3/4
 - -seal 2x6 at ceiling in garage
 - -exterior patio door needs 2 three inch screws in each hinge

Comments: