

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215682
Address: 4405 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Failed	Friday, April 28, 2023

Corrective Action Required:

1	Misc	-Stair rise from 1st to second (wood) floor is over 3/8 difference 7 3/4 steps top step 7 inches -basement stair to carpet platform stair riser is over 7 3/4.
		04/28/2023 -New carpet that is tacked in place on the second floor at the staircase will not meet code - basement stair to carpet platform will not allow enough room for proper foot tread

Comments: