CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20231091Address:2123 SW OSAGE DR, LEES SUMMIT, MO 640822121 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Control		Kyle Beard	Failed	Friday, July 07, 2023
Corrective	Action Required:			
1	Miscellaneous Correction	-2121 SW Osage needs erosion control along the east side of property		
Corrective Action Required:				
2	Miscellaneous Correction	Erosion control is still needed around the perimeter of the property. Erosion control along the east side of property has been noted before and has never been addressed. This is the third warning. This will be a two day warning that erosion control is needed and control measures need to be addressed before fees may be issued		
Corrective	Action Required:			
3	Misc	Erosion control around pe	rimeter is needed	

Comments: