CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20221047Address:795 NE ALGONQUIN ST, LEES SUMMIT, MO 64064797 NE ALGONQUIN ST, LEES SUMMIT, MO
64064793 NE ALGONQUIN ST, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Wednesday, August 09, 2023
Partial Correction:			
1 Misc Corrective Action Required:	**PROVIDE GRAVEL AT LOT ENTRANCE		
3 Miscellaneous Correction	795		
	 All corners need to be nailed off every 12 inches on center Gas line to fireplace is not connected Gas line in basement is not grounded Air return in stairwell needs to be sealed where wire is running through it Roof sheathing rated assembly has a hole in it above master bedroom 		
	 797 Top plate in garage against entry wall is broken and needs to be repaired for proper fire blocking All corners need to be nailed off every 12 inches on center Gas line to fireplace is not installed Front entry bathroom has a non rated 4 foot piece of roof sheathing decking up against the fire assembly wall Fire rated assembly is not vertically blocked off every 10 feet on center One stud in utility is broken Air return in stairwell needs to be sealed off from wiring holes 		

Comments: