

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20216461
Address: 3132 SW SUMMIT VIEW TRL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Mitchell Schwarz	Passed	Thursday, October 19, 2023

Informational:
1 Misc

erosion control back in compliance
Mitchell Schwarz 04/25/2022 9:54 AM

9-12-22 RH. Erosion control is in place and in working order.

10-24-22 RH. Erosion control is in place and in working order.

10-31-22 RH. Erosion control is in place and in working order.

11-7-22 RH. Erosion control is up in working order.

11-14-22 RH. Erosion control is up and in working order.

11-21-22 RH. Erosion control is up and in working order.

11-28-22 RH. Erosion control is up and in working order.

12-12-22 RH. Erosion control is up and in working order.

12-27-22 RH. Erosion control is up and in working order.

1-9-22 RH. Erosion control is up and in working order.

2-13-23 RH. Erosion control is up and in working order.

2-22-23 RH. Erosion Control is up and in working order.

2-27-23 RH. Erosion Control is up and in working order.

3-3-23 RH. Erosion Control is up and in working order.

3-14-23 RH. Erosion control is up and in working order.

3-17-23 RH. Erosion control is in working order.

3-22-23 RH. After the rain even from yesterday erosion control is in working order.

4-3-23 RH. Erosion control is up and in working order.

4-18-23 RH. Erosion control is up and in working order.

4-20-23 RH. Erosion control is up for street inlet next to entrance of site but silt fence is down. It needs repaired.

4-21-23 RH. Erosion control was repaired around the jobs site and is in compliance.

5-1-23 RH. Erosion control is in place and in working order.

5-16-23 RH. Erosion control is in place and in working order.

5-22-23 RH. Erosion control is up in working order.

5-24-23 RH. Erosion control is up and in working order.

6-5-23 BR. Erosion control is up and working order.

Informational:
2 Misc

Comments: