## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20216100

Address: 4813 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Tuesday, October 31,

Residential 2023

Corrective Action Required:

1 Misc -Fb plumbing space at rear hearth room wall

- -Nail corner studs w/16d @12" oc or equivalent nailing
- -Provide CSPF walls at rear dining room per plan \*\*Not framed per code. Please see the plan page 2/S505; min double 2x12 header is required; nail siding per 2/S505 detail; reinstall electrical
- -Strap exterior wall top plate where bored more than 50% \*\*At half bathroom
- -Complete garage duct/plumbing spaces and fire block as required \*\*Fire block space from soffit space
- -Provide attic access to roof space \*\*Staple wiring along the joists and away from attic access opening. Wiring running across the top of joists where within 6 ft if the attic access opening shall be protected with running board
- -Strap top plate where lapped less than 24" at master shower wall plates
- -Interior braced wall at kitchen /garage wall will be per GB method. Call for

inspection of nailing pattern when ready

\*\*OK TO INSULATE

**Comments:**