## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20231955Address:2125 SW RUTHERFORD DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Control		Kyle Beard	Failed	Monday, November 06, 2023
Corrective Action Required:				
1	Misc	Erosion control in not installed and is required. Erosion control must be in place before calling in for the next inspection after under slab plumbing		
Corrective Action Required:				
2	Miscellaneous	Erosion control is missing along the east side of the property and the Southeast corner. Full erosion control must be maintained until full C of O		
	Correction			
Corrective Action Required:				
3	Miscellaneous	Some erosion control is missing or torn down. Full erosion control mus		
	Correction	maintained until occupan	су	
Corrective Action Required:				
4	Miscellaneous Correction		hissing or torn down. Full er cy. No further inspections v lace.	

**Comments:**