

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOMCOM20230057

Address: 451 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081443 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081445 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081447 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081449 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081453 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081441 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Shawn Hoffman	Failed	Tuesday, January 30, 2024

Corrective Action Required:

1	Misc	441 - OK to insulate 443 • OK to insulate 445 • OK to isolate 447 - Missing insulation in gap demising wall third floor back bathroom also master bathroom - 449 - Missing rock wool at 1" gap of demising wall top plate third floor multiple locations - 451 - Extend demising wall to exterior wall second floor pantry - Missing rock wool third floor demising wall top plate back bathroom - 453 - Fire block HVAC chase (Finnish) all openings and gaps top on second floor (
---	------	---

- stop vertical to horizontal fire and gasses into joists space
- Continue demising wall to exterior wall at second floor pantry
 - Address top plate master bedroom third floor (blocks)

Comments: