

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20235952
Address: 1932 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Kyle Beard	Failed	Wednesday, January 31, 2024

Informational:

1	Miscellaneous Correction	Erosion control is in place at the time of sewer inspection. Full erosion control must be maintained until full CofO
---	--------------------------	--

Corrective Action Required:

2	Miscellaneous Correction	Erosion control is damaged and not effective at the front of the lot. Dirt and gravel is in the street. Clean street and repair or replace damaged erosion measures. Full erosion control must be maintained until CofO. 01/29/24 KBEARD
---	--------------------------	---

Corrective Action Required:

3	Miscellaneous Correction	Erosion control is damaged and not effective at the front of the lot. Dirt and gravel is in the street. Clean street and repair or replace damaged erosion measures. Erosion control is needed across the street where the plumbers left a mound of dirt.
---	--------------------------	---

As Ethan and I discussed verbally at a earlier date, the storm drain in the backyard needs full erosion control so mud and debris does not enter it

Have full erosion control in place before scheduling any inspections. No inspections will be conducted until full erosion control is completed
01/31/24 K.Beard

Comments: