CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20235952

Address: 1932 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Underslab Plumbing Inspection Kyle Beard Not Ready Monday, February 05,

- Residential 2024

Corrective Action Required:

1 Miscellaneous Snow/ice is still present in the footing and not all plumbing pipe can be seen

Correction or inspected.

Address erosion control before scheduling any inspections.

01/31/24 KBEARD

Corrective Action Required:

2 Miscellaneous Full erosion control includes LOT ACCESS under Lee's Summit erosion

Correction &sediment control standards. Have lot access addressed before scheduling

any inspections

Comments: