CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213809

Address: 3829 SW MARYVILLE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Not Ready Thursday, February 08,

Residential 2024

Partial Correction:

1 Miscellaneous - no pier inspection on file

Correction - Provide (2) 1/2" through bolts or equivalent at the post to beam

connections at deck

- Provide security screws at exterior doors

(No improvements were made)

Walk you property before scheduling a inspection

Not ready for re inspection

Partial Correction:

2 Miscellaneous -Provide (2) 1/2" through bolts or equivalent at the post to beam connections

Correction at deck

Provide security screws at exterior doorsPay \$75 fee associated with this permit

Corrective Action Required:

3 Miscellaneous -Deck beam connection to support is not installed R507.5.2 and figure

Correction R507.5.1 (2)

-House locked and could not verify security screws at doors

Comments: