## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20234049Address:2210 SW OSAGE DR, LEES SUMMIT, MO 640822208 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Not Ready	Thursday, February 08, 2024
Corrective Action Required: 3 Miscellaneous Correction	2208 SW Osage.	Occupancy (3)	
	Back deck electrical outlets has a gap around it and needs to be sealed Back deck stair pad to ground is not installed Backyard security light can not be readily accessible under 8 feet off the deck Hatch is missing under the stairwell for Fire blocking Guard rail is required on the front porch Exterior of the property was not ready for inspection Piers for back deck was never inspected		
	2210		
	Backyard security light can not be readily accessible under 8 feet off the deck Back deck stair pad to ground is not installed First to second step going from the dining room to upstairs has a riser height of greater than the allowed 3/8 of an inch Hatch under the stairwell is not installed for Fire blocking Hot water tank whip needs to be secured at the joist above Exterior of the property was not ready for inspection Driveway and sidewalk inspections were not passed		

Failed. No improvements were made. Not ready

**Comments:**