CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20236311

Address: 420 SW LONGVIEW BLVD, Unit:200, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling Inspection Khanh Nguyen Failed Thursday, February 15,

2024

Corrective Action Required:

1 Misc -Support ceiling light fixtures

-Cannot use ceiling grid support wires to support the MC cable. Install independent support wires for the MC cables and identify these with color $\,$

tags, paint, other other means

-Secure all flexible raceways within 12" of boxes; secure FMC every 3 ft

-Secure EMT raceway within 3 ft of the boxes

-Provide exhaust fans for restrooms

Comments: