

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220641
Address: 3537 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Not Ready	Monday, March 18, 2024

Corrective Action Required:

2	Miscellaneous Correction	3537 SE Corbin. Occupancy (2) Sod to siding in the back yard needs to be a minimum of 6 inch clearance Seal top of service meter Back side of exterior a/c unit has an open trench and will not properly drain Submit as graded plot plan, due to the backyard not matching the existing plot plan TCO passed 02/13/24 KBEARD TCO extension requested on 03/14/24. No response from request. No improvements were made during a virtual drive bye. 03/14/24 Not ready fee assessed 03/18/24. KBEARD
---	--------------------------	---

Comments: