CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20234721

Address: 2004 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822006 SW HOLDBROOKS DR, LEES SUMMIT,

MO 640822008 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822002 SW HOLDBROOKS

DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Not Ready Monday, March 18,

Residential 2024

Corrective Action Required:

2 Miscellaneous 2002 SW Holdbrooks. Occupancy (3)

Correction
-Bottom step to ground pad at back deck is has a riser height of 8 1/4 inch

high. Code is no more than a 7 3/4 inch in riser height

ingli. Code is no more than a 7 3/4 mcm in riser he

-Exterior is not ready for inspection

2204

-Bottom step to ground pad at back deck has a riser height of 8 1/2 inches in height. Code is no more than a 7 3/4 inch in riser height

-Exterior is not ready for inspection

2006

-Riser height on the back deck stairs exceed the allowable 7 3/4 of an inch

-Exterior is not ready for inspection

2008

-Back deck lower step is over the allowable 7 3/4 riser height

-Exterior is not ready for inspection

No response from TCO extension request sent 03/13/24. Visual drive bye indicated no improvements were made since TCO Not ready fee added 03/18/24. KBEARD

Comments: