CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20236390

Address: 3204 SW ARBOR SOUND DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Monday, March 18,

Residential 2024

Corrective Action Required:

1 Misc

-seal penetrations right of patio slider

-missing lib bracing at pantry-missing cspf strapping bed 1-bed 1 cspf nailing incorrect

-complete vent stack at bed 1 closet

-missing multiple truss hangers throughout

-furr out for bath vent above bed 4

-block wall space to ceiling space at beam bed 4 -seal top plate penetrations in bed 3/4 bath

-seal wall space into ceiling space bed3 see furr down

-seal wall space to ceiling space around beam in rec room NW beam

-bond gas line

Comments: