CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20241652

Address: 1020 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Electrical Service Inspection Khanh Nguyen Failed Friday, April 05, 2024

Corrective Action Required:

1 Misc -Only one grounding electrode conductor for each grounding rod clamp

-Grounding rods must be fully driven down into soil

-Secure on-ground raceways in place. Put rock or soil onto it

-Install proper size breakers for conductor ampacity

-Connect the grounding electrode conductor inside the service disconnect to

the service grounded bus bar (middle bus bars)

-Provide a grounded neutral feeder conductor to trailer disconnect; isolate

the neutral conductors from the equipment grounding conductors; bond the

enclosure

-Remove the bonding screw from the neutral bus bar; connect the feeder

equipment grounding conductor to the EGC bus bar where the grounding $% \left(\mathbf{r}\right) =\left(\mathbf{r}\right)$

electrode conductor is connected to

Comments: